HORIBA INSTRUMENTS LIMITED



KYOTO CLOSE SUMMERHOUSE ROAD MOULTON PARK NORTHAMPTON NN3 6FL

TELEPHONE FAY

01604 671166 01604 671080

REGISTERED NUMBER 1332851 ENGLAND

RAS/EM

Service Notes 1996 RAC Rally

Vehicle 1 - Transit, Vehicle 2 - Espace

Leg 1 - Saturday 23rd November 1996

Service Zone A Penrith.

Attend - Vehicle 2

Tasks - Refuel after long road section.

Special requirements - none.

Service Park B Riccarton

Attend - Vehicles 1 & 2

Tasks - Service following SS1, refuel.

Special Requirements - Light Pod to be fitted.

Service Park C Kielder

Attend - Vehicles 1 & 2

Tasks - Service following SS2,3,4 and 5, refuel.

Special Requirements - none



Service Park D Hexham

Attend - Vehicles 1 & 2

Tasks - Service following SS6, refuel.

Special Requirements - Espace to stay close to car following service, via A68, then wait on A68 adjacent to SS7, Hamsterley. Transit proceeds direct, via A69 / A1 to Service Point F, Leeds Elland Road.

Service Point E Barton

Attend - Vehicle 2.

Tasks - Service following SS7, refuel.

Special Requirements - none

Service Park F Leeds

Attend - Vehicles 1 & 2

Tasks - Service following SS8 and 9, refuel.

Special Requirements - Remove Light pod and ensure jump leads are put into car. Jackets for Crew.

Espace collects Crew from Parc Ferme



Leg 2 Sunday 24th November 1995

Espace takes Crew to Parc Ferme. Vehicle 1 proceeds direct to Service Point H, Chesterfield.

Service Zone G Leeds

Attend - Vehicle 2.

Tasks - General Check and refuel if necessary (unlikely).

Special Requirements - Remove jump leads from car. Espace to stay close and escort car from SS10 Leeds to SS11 Chatsworth.

Service Point H Chesterfield

Attend - Vehicles 1 & 2.

Tasks - Service following SS10 and 11, refuel.

Special Requirements - none.

Service Point I Donnington

Attend - Vehicles 1 & 2

Tasks - Service following SS12, refuel.

Special Requirements - Fit light Pod, Espace to stay close to car upon departure and shadow to Chester.



Service Park J Chester

Attend - Vehicles 1 & 2

Tasks - Service following SS13,14,15,16,and 17, refuel.

Special Requirements - Leave Light Pod ON and ensure jump leads are put into car. Jackets for Crew.

Espace to collect Crew from Parc Ferme.

Leg 3 Monday 25th November 1996

Espace takes Crew to Parc Ferme. Vehicle 1 proceeds direct to Service Park L, Dylife.

Service Zone K Oswestry

Attend - Vehicle 2.

Tasks - General Check and refuel.

Special Requirements - Remove jump leads from car. Leave light pod ON.

Service Park L Dylife

Attend - Vehicles 1 and 2.

Tasks - Service following SS18, refuel.

Special Requirements - Remove Light Pod, Espace continues to Service Park M via A44 and Transit proceeds to Service Park M via Machynlleth.



Service Park M Aberystwyth

Attend - Vehicles 1 and 2.

Tasks - Service following SS19 and 20, refuel.

Special Requirements - none.

Service Park N Dolgellau

Attend - Vehicles 1 and 2.

Tasks - Service following SS21, 22 and 23, refuel.

Special Requirements - none.

Service Point O Brenig

Attend - Vehicles 1 and (if possible) 2. This Service Point is restricted to one service vehicle per team, but the Espace may be able to blag their way in - suck it and see!

Tasks - Service following SS24 and 25, refuel.

Special Requirements - Fit light Pod.

Service Point P Bodelwyddan

Attend - Vehicles 1 and 2

Tasks - Service following SS26 and 27, refuel as needed.

Special Requirements - Give car a good clean for final run in and possibly remove light pod.Jackets for Crew.


All vehicles proceed to Chester Racecourse for the finish.

Espace collects Crew from Parc Ferme.



Tuesday 26th November 1996

Espace takes Trevor to collect car from Parc Ferme and after returning to Robin Hood team disperses to return home.



NETWORK Q RAC RALLY

